

| |
|--------------------------|
| TABLE OF CONTENTS |
|--------------------------|

| | Page |
|--|-------------|
| 1.0 INTRODUCTION | 1 |
| 1.1 Background | 1 |
| 1.2 Benchmarking | 2 |
| 1.3 Organization of Report..... | 4 |
| 2.0 TECHNICAL APPROACH | 5 |
| 2.1 Overview | 5 |
| 2.2 Literature Search | 5 |
| 2.3 Surveys..... | 6 |
| 2.3.1 Rationale for Surveys | 6 |
| 2.3.2 Selection and Qualification of Companies..... | 7 |
| 2.3.3 Development of Survey Form | 9 |
| 2.4 Interviews | 10 |
| 3.0 RESULTS | 13 |
| 3.1 Literature Search Results..... | 13 |
| 3.2 Survey Results..... | 13 |
| 3.3 Interview Results..... | 16 |
| 3.4 Overall Discussion | 17 |
| 3.5 General Findings | 20 |
| 3.5.1 The Environment..... | 20 |
| 3.5.2 The Practices | 21 |
| 3.6 Specific Findings..... | 22 |
| 4.0 CONCLUSIONS | 27 |
| 4.1 The Practices | 27 |
| 4.1.1 Reliability Tasks..... | 27 |
| 4.1.2 Approach to Achieving Reliability..... | 28 |
| 4.2 The Contracting Environment..... | 28 |
| 4.3 The Benchmarks..... | 29 |
| 4.4 Other Keys to Success..... | 29 |
| 5.0 AREAS REQUIRING ADDITIONAL RESEARCH | 31 |
| APPENDIX A: DEFENSE ACQUISITION REFORM | |
| APPENDIX B: LITERATURE SEARCH RESULTS | |
| APPENDIX C: SURVEY FORMS | |
| APPENDIX D: INTERVIEW QUESTIONS AND NOTES | |
| APPENDIX E: TERMS AND DEFINITIONS | |
| APPENDIX F: RAC PRODUCT ORDER FORM | |

LIST OF FIGURES

| | |
|---|----|
| Figure 1: Xerox's Ten-Step Model for Benchmarking | 3 |
| Figure 2: Relative Importance of Reliability Tasks..... | 15 |
| Figure 3: CAD/CAM Facilitates Customer Focus | 17 |

LIST OF TABLES

| | |
|--|----|
| Table 1: Industries Identified for Study..... | 8 |
| Table 2: Criteria for Identifying Candidate Companies | 8 |
| Table 3: List of Companies Interviewed | 11 |
| Table 4: Overview of Companies Surveyed and Interviewed..... | 13 |
| Table 5: Most Important Reliability Tasks According to Survey | 14 |
| Table 6: Anecdotal Comments..... | 19 |
| Table 7: Reliability Tasks Grouped by Objective | 27 |
| Table 8: Characterizing the Commercial Sector Contracting Environment..... | 28 |